


tap 10-32
thru to
cross hole



COIL SUPPORT
mat'l - steel
4 req'd

5